

## OIL LIGHT RESET PROCEDURES

2007 BMW 525I

===== MODEL # 1: ALL MODELS WITH UNDER HOOD DIAGNOSTIC CONNECTOR  
=====

To reset indicator after performing and engine oil and filter change. Turn off all accessories and place ignition switch in ON position with engine stopped. Position reset tool and, if necessary, adapter into diagnostic connector. Depress and hold yellow "OIL SERVICE" button of reset tool. Green function control lamp should be illuminated. After approximately 10 seconds, the yellow lamp should illuminate for approximately 3 seconds, then turn off. Release tool oil service button, then check instrument panel LED's. At least one additional green LED should be illuminated and the yellow or red LED and "OIL SERVICE" indicator should be off.

This vehicle does NOT have a diagram.

Portions are Copyright(c) 2007 by Motor Information Systems,  
a division of Hearst Business Publishing, Inc. All rights reserved.